

EPA Region 5 Records Ctr.



295611































































































## FIELD PHOTOGRAPHY LOG SHEET

SITE NAME: Seymour of Sycamore

PAGE 1 OF 6

U.S. EPA ID: ILD005100789 TDD: F058807006PAN: FIL0652PADATE: > 8-13-88TIME: > 13:45DIRECTION OF  
PHOTOGRAPH:> NWEATHER  
CONDITIONS:> hot, humid> 97°F

PHOTOGRAPHED BY:

> R. BayerSAMPLE ID  
(if applicable):> N/ADESCRIPTION: > The front of the Seymour of Sycamore  
> plant. The sign is facing Crosby Street.DATE: > 8-13-88TIME: > 13:45DIRECTION OF  
PHOTOGRAPH:> NNWWEATHER  
CONDITIONS:

&gt;

&gt;

PHOTOGRAPHED BY:

> R. BayerSAMPLE ID  
(if applicable):> N/ADESCRIPTION: > The loading dock for the Seymour of  
> Sycamore paint plant.




FIELD PHOTOGRAPHY LOG SHEET

SITE NAME: Seymour of Sycamore

PAGE 2 OF 6

U.S. EPA ID: ILD005100789 TDD: F05-8807-006

PAN: FIL0652P4



DATE: > 8/13/88 TIME: > 13.31 DIRECTION OF PHOTOGRAPH: > W PHOTOGRAPHED BY: > R. Bayes

WEATHER CONDITIONS: > hot, humid 97°F SAMPLE ID (if applicable): > N/A


DESCRIPTION: > Views of Seymour of Sycamore, Inc. paint plant from Maestry Drive. The bare field is part of the plant's property.



## FIELD PHOTOGRAPHY LOG SHEET

SITE NAME: Seymour of SycamorePAGE 3 OF 6U.S. EPA ID: ILD005100789 TDD: F05-8807-006PAN: FILO652 PADATE: > 8/13/88TIME: > 13:32DIRECTION OF  
PHOTOGRAPH:> WNWWEATHER  
CONDITIONS:> hot, humid> 97°F


PHOTOGRAPHED BY:

> R. BayerSAMPLE ID  
(if applicable):> N/ADESCRIPTION: > View from Maertz Drive of rear of  
> plant. Note fenced area and piles of soil  
> partially covered with plastic.DATE: > 8/13/88TIME: > 13:30DIRECTION OF  
PHOTOGRAPH:> EWEATHER  
CONDITIONS:

&gt;

&gt;

PHOTOGRAPHED BY:

> R. BayerSAMPLE ID  
(if applicable):> N/ADESCRIPTION: > The City of Sycamore's municipal well #6,  
> located on Maertz Drive



## FIELD PHOTOGRAPHY LOG SHEET

SITE NAME:

Seymour of Spcamore

PAGE 4 OF 6

U.S. EPA ID:

ILD005100789TDD: F05-8807-006PAN: F1L0652PADATE: > 8/13/88TIME: > 13:40DIRECTION OF  
PHOTOGRAPH:> SSEWEATHER  
CONDITIONS:> hot, humid> 97°F

PHOTOGRAPHED BY:

> R. BayerSAMPLE ID  
(if applicable):> N/A

DESCRIPTION: > Photo is taken from the back of the  
> plant from the former railroad bed. Note fence  
> enclosing covered pit area.

DATE: > 8/13/88TIME: > 13:40DIRECTION OF  
PHOTOGRAPH:> SSEWEATHER  
CONDITIONS:

&gt;

&gt;

PHOTOGRAPHED BY:

> R. BayerSAMPLE ID  
(if applicable):> N/A

DESCRIPTION: > Close-up shot of covered pit. Freshly spread  
> soil (darker material) and a lighter unknown  
> material lie to the west of the pit.



FIELD PHOTOGRAPHY LOG SHEET

SITE NAME: Seymour of Sycamore

PAGE 5 OF 6

U.S. EPA ID: ILD005100789 TDD: F05-8807-006

PAN: F/L0652PA

DATE: > 8/13/88

TIME: > 13:42

DIRECTION OF PHOTOGRAPH:

> SSE

WEATHER

CONDITIONS:

> hot, humid

> 97°F

PHOTOGRAPHED BY:

> R. Bayer

SAMPLE ID

(if applicable):

> N/A



DESCRIPTION: > View of employee parking lot, spread  
> light-colored material, and pipes.

DATE: > 8/13/88

TIME: > 13:42

DIRECTION OF PHOTOGRAPH:

> S

WEATHER

CONDITIONS:

>

>

PHOTOGRAPHED BY:

> R. Bayer

SAMPLE ID

(if applicable):

> N/A



DESCRIPTION: > Above-ground storage tanks located to  
> the west of the excavated pit.



FIELD PHOTOGRAPHY LOG SHEET

SITE NAME: Seymour of Sycamore

PAGE 6 OF 6

U.S. EPA ID: ILD005100789 TDD: F05-8807-006

PAN: F1L0652PA

DATE: > 8/13/88

TIME: > 13:45

DIRECTION OF  
PHOTOGRAPH:

> SSW

WEATHER  
CONDITIONS:

> hot, humid

> 97°F

PHOTOGRAPHED BY:

> R. Bayer

SAMPLE ID  
(if applicable):

> N/A



DESCRIPTION: > Piles of soil located to the back and

> just west of the above-ground storage tanks. Plastic  
sheets partially cover the piles.